

# Revision History / 変更履歴

Version 2.3.0 (4 October 2022) - English

## 1. New Features

- Added support for PW4NX printer.
- Added support for PW208mNX printer.
- Added Auto Switch Group setting for CLNX (incl. non-Plus, Plus, J, J Plus), CT4-LX, and HC4-LX printer series.
- Added NFC setting for all supported printer series.
- Added SOS (SATO Online Services) setting for CLNX (incl. non-Plus, Plus, J, J Plus), CT4-LX, HC4-LX (FW >6.5.0), FX3-LX\_Ln, and PW2NX (FW >3.5.0) printer series.
- Added PW2NX settings from firmware V3.5.0.
- Added support for Japanese and Chinese (simplified) language.

## 2. Enhancements

- Added printer function to auto retrieve data when USB port is opened.
- Added Japanese version of terms of use for application logs.
- Send SBPL Command function: Improved speed for sending large data via USB interface.
- Added function to reboot printer when changing certain printer settings.
- Upload Fonts and Graphics functions: Improved stability.

## 3. Fixed Bugs

- Fixed: Clone Configuration function is not working for USB interface.
- Fixed: Cannot upload firmware via USB interface and Wi-Fi direct.
- Fixed: Cannot upload firmware when the file name contains some specific special characters.
- Fixed: Printer Discovery function unable to discover some of the printers.
- Fixed: Status Monitoring issue whereby sometimes the correct status is not reflected.
- Fixed: Configuration settings are exported wrongly for NFC tool.
- Fixed: Cannot print out data sometimes when using Load From File. (Send SBPL Command function)
- Fixed: Application crashes when loading large files. (Send SBPL Command function) Now a file size limit of 500KB is applied.
- Fixed: SBPL Command Preview function unable to preview large print data.
- Fixed: Edit Printer Information page is stuck when user click the Submit button.
- Fixed: Windows service generates binding exception due to port 5000.

## 1. 新機能

- PW4NXプリンタに対応しました。
- PW208mNXプリンタに対応しました。
- グループ自動切替設定をCLNX (non-Plus、Plus、J、J Plus含む)、CT4-LXおよびHC4-LXプリンタシリーズに追加しました。
- 対応している全てのプリンタシリーズにNFC設定を追加しました。
- SATOオンラインサービス(SOS)の設定をCLNX (non-Plus、Plus、J、J Plusを含む)、CT4-LXおよびHC4-LX(FW6. 5. 0以降)、FX3-LX\_Ln、PW2NX (FW3. 5. 0以降)プリンタシリーズに追加しました。
- PW2NX (FW3. 5. 0)の設定に対応しました。
- 言語設定に日本語、簡体中国語を追加しました。

## 2. 改良

- プリンタ自動検出: USB接続プリンタが検出可能になりました。
- アプリケーションログデータの利用条件に日本語版を追加しました。
- SBPL送信機能: 大容量データを送信した際の通信速度を改善しました。
- 特定のプリンタ設定変更時に再起動を要求する通知を追加しました。
- フォント・画像アップロード機能の安定性を改善しました。

## 3. 不具合修正

- クローン設定機能: USB接続で動作しない問題を修正しました。
- USBおよびWiFiダイレクト接続でファームウェアがアップロードできない問題を修正しました。
- 特定の文字をファイル名に含むファームウェアがアップロードできない問題を修正しました。
- プリンタ自動検出機能で見つからないプリンタがある問題を修正しました。
- ステータス監視機能でステータスが正確に表示されない問題を修正しました。
- NFCツールで設定が正しくエクスポートされない問題を修正しました。
- SBPL送信機能: 「ファイルから読み込む」を使用した際に印字データが印刷されない問題を修正しました。
- SBPL送信機能: 大容量ファイルを読み込むとアプリケーションがクラッシュする問題を修正しました。読み込むファイルサイズを500KBまでに制限しました。
- SBPL送信機能: 大容量ファイルをプレビューできない問題を修正しました。
- 「確定」ボタンをクリック後、プリンタ情報が更新されない問題を修正しました。
- Windowsサービス: ポートバインディング例外を修正しました。